

Safety and security rules to be followed in Fluid Mechanics and Machinery Lab

1. Always wear shoes before entering lab.
2. Do not touch anything without the permission of instructor/lab assistant.
3. Read carefully the lab manual before performing experiments.
4. Check electrical connections before starting the equipment.
5. Do not put your hands while the machine is in operation.
6. Do not tamper measuring instruments.
7. Do not open the casing of the equipment.
8. Do not unplug any electrical connection.
9. Switch off the power supply to the experimental setup on completion of the experiment.
10. Do not leave chemical containers on the working tables.
11. Use safety goggles wherever necessary.